



Španija

Dobro stanje

CE,
EPA

8.812 Hours

2019

103.500 €

Mašina

DOBRO STANJE

Sažetak inspekcije

Komentari o inspekciji

- ✓ 113 Odobren
- ⚠ 1 Nesavršenosti
- ✗ 1 Problemi

Configuration

General



Air-conditioning



CE plate



EPA Label

Specific

- Auxiliary hydraulic system
- Counterweight
- Steering control lever (stic)
- Third valve
- Auto switch
- Differential, standard
- Damping control
- Automatic lubrication
- Differential lock /unlock
- Complementary address
- Lighting system

Lokacija



Calle Latón, 2
28500 Arganda del Rey (Španija)

Link do datoteke



[CATERPILLAR 926M](#)

CYCLION