



Spain

Good condition

CE, EPA

3,977 Hours

2020

207,000 €

Machine status

GOOD CONDITION

Inspection summary

- 74 Approved
- 6 Imperfections
- 2 Problems

Inspection comments

Pta de la cabina agarrada. Espejo lat.dcho roto.Cerradura sup.hueco motor no cierra. Holgura en las planchas de las patas. La direcció n se queda dura. Pintura en general oxidada. Luz int. dcho luce.

Configuration

General

Air-conditioning



EPA Label

Specific

- Coupling
- Stabilizer
- Auxiliary hydraulic system
- Elevated cabin
- Boom
- Stabilizers
- Automatic lubrication
- Long stick

Location



Calle Latón, 2
28500 Arganda del Rey (Spain)

Link to file



[CATERPILLAR MH3022](#)

CYCLOCIN