

CATERPILLAR 926M

Wheel loaders  
#LTE06883



Spain

Good condition

CE,  
EPA

8,812 Hours

2019

103,500 €

Machine status

GOOD CONDITION

Inspection summary

Inspection comments

- ✓ 113 Approved
- ⚠ 1 Imperfections
- ✗ 1 Problems

Configuration

General

- Air-conditioning
- EPA Label



CE plate

Specific

- Auxiliary hydraulic system
- Counterweight
- Steering control lever (stic)
- Third valve
- Auto switch
- Differential, standard
- Damping control
- Automatic lubrication
- Differential lock /unlock
- Complementary address
- Lighting system

## Location



Calle Latón, 2  
28500 Arganda del Rey (Spain)

## Link to file



[CATERPILLAR 926M](#)

CYCLOTRON