



Spain

Good condition

CE,
EPA

1,929 Hours

2005

184,500 €

Machine status

GOOD CONDITION

Inspection summary

- 87 Approved
- 13 Imperfections
- 7 Problems

Inspection comments

Equipo en buen estado de funcionamiento. Necesita lavado. Necesario sustituir baterías. Caja sobredimensionada con refuerzos en articulación cilindros.

Configuration

General



CE plate



Air-conditioning

Product link



EPA Label

Specific

- Traction aid (aeta)
- Payload metering system
- Box exhaust gases
- Automatic lubrication
- Retarder
- Electrical start

Location



Calle Latón, 2
28500 Arganda del Rey (Spain)

Link to file



[CATERPILLAR 773E](#)

CYCLOTRON