

CATERPILLAR M318

Wheel excavators
#KE700198



Spain

Very good condition

CE

4,040 Hours

2020

156,000 €

Machine status

VERY GOOD CONDITION

Inspection summary

Inspection comments

- ✓ 86 Approved
- ⚠ 0 Imperfections
- ✗ 0 Problems

Configuration

General

- Air-conditioning
- EPA Label



CE plate

Specific

- Stabilizers
- Automatic lubrication
- Auxiliary hydraulic system
- Coupling
- Ultra-low sulfur diesel fuel
- Stabilizer
- Boom

Location



Calle Latón, 2
28500 Arganda del Rey (Spain)

Link to file



[CATERPILLAR M318](#)

CYCLOTRON