



Espagne

Bon état

CE,
EPA

1 929 Heures

2005

184 500 €

État de la machine

BON ÉTAT

Résumé de l'inspection

- ✓ 87 Approuvé
- ⚠ 13 Imperfections
- ✗ 7 Problèmes

Commentaires sur l'inspection

Equipo en buen estado de funcionamiento. Necesita lavado. Necesario sustituir baterías. Caja sobredimensionada con refuerzos en articulación cilindros.

Configuration

Général



CE plate



Air-conditioning

Product link



EPA Label

Spécifique

- Traction aid (aeta)
- Payload metering system
- Box exhaust gases
- Automatic lubrication
- Retarder
- Electrical start

Localisation



Calle Latón, 2
28500 Arganda del Rey (Espagne)

Lien vers le fichier



[CATERPILLAR 773E](#)

CYCLOC